

TX RX Systems Inc.  
8625 Industrial Parkway  
Angola, NY 14006  
716-549-4700  
Fax: 716-549-4772

October 21, 2005

Timco  
c/o Ultratech  
3000 Bristol Circle  
Oakville, Ontario  
Canada L6H 6G4

Dear Sir,

This letter is in response to your request for verification of the addition which has been included into the signal booster model number 61-83B-50, FCC ID: EZZ5PI618350, IC ID: 1940A-PI618350. This addition includes an assembly (Fig. 1) added to the backup DC power input terminals to reduce the conducted emissions (referred to as the 30 VDC supply by Ultratech).





Fig.1



This assembly consists of three capacitors and one inductor. The capacitors are Panasonic part number ECQ-E2225KB, which are 2.2  $\mu$ fd, 250V, metallized polypropylene film, non-polarized. TX RX System has assigned part number 8-20967. The inductor is a JW Miller part number 8108, which is 1mH, 10A inductor. TX RX has assigned part number 8-21128. This assembly has already been added to the bill of materials for this model booster, and will be configured in all of these boosters prior to shipment.

A handwritten signature in black ink, appearing to read 'Michael Fetto', with a long horizontal line extending to the right.

Michael Fetto  
Director of Product Development