

Hi Ruby,

As discussed this morning, please find attached the document changes. The changes in instruction/installation sheet can be found in the highlighted notes above the "Limitations of Smoke Detectors" section, attached below

<<wls906-433 inis eng 29004973 r003draftwp2.pdf>>

The changes in the software can be found in the first paragraph of the first page and the timing diagram in the second page, attached below.

<<WLS906NB433.doc>>

Regards,

Michael Yaw

-----Original Message-----

From: Michael Yaw

Sent: Monday, September 11, 2000 10:08 AM

To: 'Ruby Dulmage'

Cc: Sherwyn Welshman; Lila Vicich; Alan Hamilton; Kevin Harris

Subject: RE:

Hi Ruby,

I have got in touch with Richard Fabina. I am going to change our software and instruction/installation sheet to comply with FCC requirements. These changes will be implemented today.

Thanks and regards,

Michael Yaw

-----Original Message-----

From: Ruby Dulmage [mailto:rdulmage@ktlcanada.com]

<<mailto:rdulmage@ktlcanada.com>>

Sent: Wednesday, September 06, 2000 9:26 AM

To: Michael Yaw - DSC; Mary Parks - DSC

Subject: Fw:

Below is the reply I received from the FCC. It looks like

you are going to have to get in touch with Richard Fabina and discuss this with him.

Thanks,  
Ruby

----- Original Message -----

From: "OET" <[oetech@fccsun07w.fcc.gov](mailto:oetech@fccsun07w.fcc.gov)  
<<mailto:oetech@fccsun07w.fcc.gov>> >

To: <[rdulmage@ktlcanada.com](mailto:rdulmage@ktlcanada.com) <<mailto:rdulmage@ktlcanada.com>>  
>

Sent: September 1, 2000 6:42 PM

Subject:

> To: Ruby Dulmage, null  
> From: Katie Hawkins  
> [khawkins@fcc.gov](mailto:khawkins@fcc.gov) <<mailto:khawkins@fcc.gov>>  
> FCC Application Processing Branch  
>  
> Re: FCC ID F5300NB906  
> Applicant: Digital Security Controls Limited  
> Correspondence Reference Number: 15893  
> 731 Confirmation Number: EA96795  
> Date of Original E-Mail: 09/01/2000  
>  
>  
> If you wish to discuss the fire trouble transmission,  
please contact Richard Fabina at (301) 362-3021 or e-mail him at  
[rfabina@fcc.gov](mailto:rfabina@fcc.gov) <<mailto:rfabina@fcc.gov>> .  
>  
> The items indicated above must be submitted before  
processing can continue on the above referenced application. Failure to  
provide the requested information within 60 days of the original e-mail date  
may result in application dismissal pursuant to Section 2.917 (c) and  
forfeiture of the filing fee pursuant to section 1.1108.  
>  
> DO NOT reply to this e-mail by using the Reply button. In  
order for your response to be processed expeditiously, you must upload your  
response via the Internet at [www.fcc.gov](http://www.fcc.gov) <<http://www.fcc.gov>> , Electronic  
Filing, OET Equipment Authorization Electronic Filing. If the response is  
submitted through Add Attachments, in order to expedite processing, a  
message which informs the processing staff that a new exhibit has been  
submitted must also be submitted via Submit Correspondence. Also, please  
note that partial responses increase processing time and should not be  
submitted.

>

> Any questions about the content of this correspondence  
should be directed to the e-mail address listed below the name of the  
sender.