




DX-40




Retlif Testing Laboratories

Test Report Number R-7488
FCC ID: FA77EW




Retlif Testing Laboratories

Test Report Number R-7488
FCC ID: FA77EW



Retlif Testing Laboratories


Test Report Number R-7488
FCC ID: FA77EW



Retlif Testing Laboratories


Test Report Number R-7488
FCC ID: FA77EW

DX-40




Retlif Testing Laboratories

Test Report Number R-7488
FCC ID: FA77EW




Retlif Testing Laboratories

Test Report Number R-7488
FCC ID: FA77EW



Retlif Testing Laboratories

Test Report Number R-7488
FCC ID: FA77EW



Retlif Testing Laboratories

Test Report Number R-7488
FCC ID: FA77EW