


051045 C2PC Test Setup Photos



Rogers Labs, a division of The Compatibility Center LLC

7915 Nieman Road

Lenexa, KS 66214

Phone: (913) 660-0666

Revision 1

HVIN : 051045

Test: 260326

Test to: 47CFR Parts 2, 90 and RSS-137

File: 051045 Conf TSup

PMN : 051045

FCC ID: FIH051045

Transcore

SN: N/A

IC: 1584A-FIH051045

Date: avril 20, 2026

Page 1 of 4



Rogers Labs, a division of The Compatibility Center LLC

7915 Nieman Road

Lenexa, KS 66214

Phone: (913) 660-0666

Revision 1

HVIN : 051045

Test: 260326

Test to: 47CFR Parts 2, 90 and RSS-137

File: 051045 Conf TSup

PMN : 051045

FCC ID: FIH051045


Transcore

SN: N/A

IC: 1584A-FIH051045

Date: avril 20, 2026

Page 2 of 4



Rogers Labs, a division of The Compatibility Center LLC

7915 Nieman Road

Lenexa, KS 66214

Phone: (913) 660-0666

Revision 1

HVIN : 051045

Test: 260326

Test to: 47CFR Parts 2, 90 and RSS-137

File: 051045 Conf TSup

PMN : 051045

FCC ID: FIH051045


Transcore

SN: N/A

IC: 1584A-FIH051045

Date: avril 20, 2026

Page 3 of 4



Rogers Labs, a division of The Compatibility Center LLC

7915 Nieman Road

Lenexa, KS 66214

Phone: (913) 660-0666

Revision 1

HVIN : 051045

Test: 260326

Test to: 47CFR Parts 2, 90 and RSS-137

File: 051045 Conf TSup

PMN : 051045

FCC ID: FIH051045

Transcore

SN: N/A

IC: 1584A-FIH051045

Date: avril 20, 2026

Page 4 of 4