


Equipment photographs (Sample Modified for testing with the external switch)



Rogers Labs, a division of The Compatibility Center LLC

7915 Nieman Road

Lenexa, KS 66214

Phone/Fax: (913) 660-0666

Revision 3

HVIN : 051153 PMN: 051153

Test: 240930

File: 051153 Short Term Conf ExtPho


TransCore

FCC ID: FIH051153

IC: 1584A-051153

Date: October 25, 2024

Page 1 of 4



Rogers Labs, a division of The Compatibility Center LLC

7915 Nieman Road

Lenexa, KS 66214

Phone/Fax: (913) 660-0666 Test to: 47CFR Parts 2, 90 and RSS-137 Date: October 25, 2024

Revision 3

HVIN : 051153 PMN: 051153

Test: 240930


File: 051153 Short Term Conf ExtPho

TransCore

FCC ID: FIH051153

IC: 1584A-051153

Page 2 of 4



Rogers Labs, a division of The Compatibility Center LLC  
7915 Nieman Road  
Lenexa, KS 66214


HVIN : 051153 PMN: 051153  
Test: 240930

Phone/Fax: (913) 660-0666 Test to: 47CFR Parts 2, 90 and RSS-137 Date: October 25, 2024  
Revision 3

File: 051153 Short Term Conf ExtPho

TransCore  
FCC ID: FIH051153  
IC: 1584A-051153

Page 3 of 4



Rogers Labs, a division of The Compatibility Center LLC

7915 Nieman Road

Lenexa, KS 66214

Phone/Fax: (913) 660-0666

Revision 3

HVIN : 051153 PMN: 051153

Test: 240930

File: 051153 Short Term Conf ExtPho

TransCore

FCC ID: FIH051153

IC: 1584A-051153

Date: October 25, 2024

Page 4 of 4