



Equipment photographs



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Transcore PMN: E4 FLEX
HVIN: E4FLEXV1
Test: 230613
Test to: 47CFR Parts 2, 90 and RSS-137
File: E4FLEXV1 ExtPho



SN: Sample 1
FCC ID: FIHE4FPT90V1
IC: 1584A-E4FRSS137V1
Date: August 9, 2023
Page 1 of 3



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Transcore PMN: E4 FLEX
HVIN: E4FLEXV1
Test: 230613
Test to: 47CFR Parts 2, 90 and RSS-137
File: E4FLEXV1 ExtPho

SN: Sample 1
FCC ID: FIHE4FPT90V1
IC: 1584A-E4FRSS137V1
Date: August 9, 2023
Page 2 of 3



Rogers Labs, Inc.
4405 West 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Transcore PMN: E4 FLEX
HVIN: E4FLEXV1
Test: 230613
Test to: 47CFR Parts 2, 90 and RSS-137
File: E4FLEXV1 ExtPho

SN: Sample 1
FCC ID: FIHE4FPT90V1
IC: 1584A-E4FRSS137V1
Date: August 9, 2023
Page 3 of 3