




Test Set up for Transmitter Testing




Rogers Labs, a division of The Compatibility Center LLC
7915 Nieman Road HVIN: E6V3 PMN: E5, E6
Lenexa, KS 66214 Test: 250602 FCC ID: FIHE6PT90V3
Phone/Fax: (913) 660-0666 Test to: 47CFR Parts 2, 90 and RSS-137
Revision 1 File: E6V3 TSup

TransCore
SN: 20374184
IC: 1584A-E6RSS137V3
Date: August 8, 2025
Page 1 of 4



Rogers Labs, a division of The Compatibility Center LLC
 7915 Nieman Road HVIN: E6V3 PMN: E5, E6
 Lenexa, KS 66214 Test: 250602 FCC ID: FIHE6PT90V3
 Phone/Fax: (913) 660-0666 Test to: 47CFR Parts 2, 90 and RSS-137
 Revision 1 File: E6V3 TSup

TransCore
 SN: 20374184
 IC: 1584A-E6RSS137V3
 Date: August 8, 2025
 Page 2 of 4



Rogers Labs, a division of The Compatibility Center LLC
7915 Nieman Road HVIN: E6V3 PMN: E5, E6
Lenexa, KS 66214 Test: 250602 FCC ID: FIHE6PT90V3
Phone/Fax: (913) 660-0666 Test to: 47CFR Parts 2, 90 and RSS-137
Revision 1 File: E6V3 TSup

TransCore
SN: 20374184
IC: 1584A-E6RSS137V3
Date: August 8, 2025
Page 3 of 4



Rogers Labs, a division of The Compatibility Center LLC
7915 Nieman Road HVIN: E6V3 PMN: E5, E6
Lenexa, KS 66214 Test: 250602 FCC ID: FIHE6PT90V3
Phone/Fax: (913) 660-0666 Test to: 47CFR Parts 2, 90 and RSS-137
Revision 1 File: E6V3 TSup

TransCore
SN: 20374184
IC: 1584A-E6RSS137V3
Date: August 8, 2025
Page 4 of 4