

Once the attenuator is installed, you must connect cable 302202 (drawing 403516) to the attenuator and to the top of the PC to connect the antenna to the built-in 2.4 GHz Cisco radio. Cable 302202 is terminated at one end, as shown below. Minimize cable 302202 for maximum power (six foot minimum for FCC compliance).



Figure 2.23 **Terminated End of Cable 302202**

- 2 Terminate the other end of cable 302202, as shown in drawing 403516.
- 3 Attach the terminated end to the attenuator and attach the other end to the top of the PC. Make sure the bend radius is 3 - 4 inches.



Figure 2.24 **Cable 302202 Attached to Attenuator**