






7435A823 QAPE ES
INTEL©©'03
Dothan 533 FSB
1.86
GHz
940120A01


940120A01



7437A933 QAPF ES
INTEL©©'03
Dothan 533 FSB
2.0
GHz
940120A01


940120A01



7441A184 QDRB ES
INTEL©'03
940120A01


940120A01


MDOAD4G3I448041C0H
DDR333(2.5) 1GX16
S/N: 452XR (ADFDB1A1607H)
Warranty void if removed
ADD9608A8C-6B
940120A01


ADD9608A8C-6B
940120A01


MDOAD4F4H3450B1C0H
DDR333(2.5) 512MX8
S/N: 442TH (ADFDB290800H)
Warranty void if removed
940120A01


A-Data
940120A01



MDOAD4F3G3460D1C02
DDR 333(2.5) 256MX8
S/N:451TH (ADFDB1808012)
Warranty void if removed
94120A01


SY4521000037
P/N:18-060005-N0
1140L1017462
94120A01



MDOHY4F3G3460D1C0Z
DDR333(2.5) 256MX8
S/N: 447TR (HYFDB180801Z)
Warranty void if removed
HY5DU56822BT-J
KOR
94V-0
940120A01


R-DATA
SO200RCB
HY5DU56822BT-J
KOR
SY4521000048
P/N:16-060005-V0
1140L1017473
940120A01



TwinMOS®
P/N:M2S5I08D6APS5F081AA-T
MODEL NO:M2S5I08D-PS
S/N: 431M45M49422316
PC2700(CL2.5) 256MB DDR SO-DIMM
Warranty Void If Removed
940120A01


A2S56D30BTP
425ALM22
TAIWAN -6
940120A01


FUJITSU
MADE IN THAILAND
MANUFACTURED FUJITSU (THAILAND) CO., LTD.
MHT2040AT
LBA 78140160
DEVICE0
PIN1
JUMPER
DEVICE1
CABLE SEL.
94012OA01


94012OA01


FUJITSU
MADE IN THAILAND
60.0GB
DEVICE0
DEVICE1
CABLE SEL
94012OA01


94012OA01



FUJITSU
MADE IN THAILAND
94012OA01


94012OA01


DISK DRIVE MK6025GAS
HDD2189
S/N 842S03861
TOSHIBA CORPORATION
MADE IN PHILIPPINES
CAUTION
DO NOT DISASSEMBLE OR MODIFY.
DO NOT REMOVE ANY LABELS.
DO NOT PUSH ON THE TOP COVER.
HANDLE ONLY BY SIDES OF BASE.
AVOID GIVING SHOCK.
DO NOT COVER BREATHING HOLE.
RATTLE NOISE IS NORMAL.
940120A01


TOSHIBA
VOID WARRANTY IF SEAL BROKEN
940120A01



940120A01


940120A01


940120A01


940120A01


CD-R/RW/DVD-ROM DRIVE
940120A01


940120A01