



INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES

Internal photos




INTERTEK TESTING SERVICES

Internal photos





INTERTEK TESTING SERVICES

Internal photos





INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 17020914HKG-001
FCC ID: G2R-1695
IC: 1135D-1695

INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 17020914HKG-001
FCC ID: G2R-1695
IC: 1135D-1695



INTERTEK TESTING SERVICES

Internal photos





INTERTEK TESTING SERVICES

Internal photos





INTERTEK TESTING SERVICES

Internal photos





INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES

Internal photos

