




Worst case configuration photo





FCC ID: G6D60806RR
IC: 9650A-60806RR

Test setup photo



FCC ID: G6D60806RR
IC: 9650A-60806RR



FCC ID: G6D60806RR
IC: 9650A-60806RR