





Plot on 6475 MHz




11:51:35 PM 05/02/2026

Plot on 6515 MHz




11:58:28 PM 05/02/2026

Plot on 6535 MHz



12:08:00 AM 05/03/2026


Plot on 6695 MHz



12:16:21 AM 05/03/2026




Plot on 6855 MHz




12:23:00 AM 05/03/2026

Plot on 6875 MHz




01:00:03 AM 05/03/2026

Plot on 6895 MHz



01:09:30 AM 05/03/2026


Plot on 6995 MHz



01:20:46 AM 05/03/2026



Plot on 7095 MHz






EUT Mode


802.11be EHT20 FullIRU

Plot on 5955 MHz




12:40:22 AM 05/05/2026

Plot on 6195 MHz




09:43:47 PM 04/29/2026

Plot on 6415 MHz



12:52:28 AM 05/05/2026


Plot on 6435 MHz



01:00:05 AM 05/05/2026




Plot on 6475 MHz




09:58:48 PM 04/29/2026

Plot on 6515 MHz




01:28:27 AM 05/05/2026

Plot on 6535 MHz



01:37:06 AM 05/05/2026


Plot on 6695 MHz



10:29:38 PM 04/29/2026




Plot on 6855 MHz




10:39:01 PM 04/29/2026

Plot on 6875 MHz




01:52:12 AM 05/05/2026

Plot on 6895 MHz



02:19:09 AM 05/05/2026


Plot on 6995 MHz



10:55:01 PM 04/29/2026



Plot on 7095 MHz






EUT Mode


802.11be EHT40 FullIRU

Plot on 5965 MHz




02:37:49 AM 05/05/2026

Plot on 6205 MHz




08:33:47 PM 04/30/2026

Plot on 6405 MHz



08:39:25 PM 05/05/2026


Plot on 6445 MHz



09:14:23 PM 05/05/2026




Plot on 6485 MHz




09:43:56 PM 04/30/2026

Plot on 6565 MHz




09:32:32 PM 05/05/2026

Plot on 6685 MHz



09:16:44 PM 04/30/2026


Plot on 6845 MHz



09:57:49 PM 04/30/2026




Plot on 6885 MHz




09:40:16 PM 05/05/2026

Plot on 6925 MHz




09:47:21 PM 05/05/2026

Plot on 7005 MHz



10:10:40 PM 04/30/2026


Plot on 7085 MHz



09:58:17 PM 05/05/2026



Plot on 6525 MHz






EUT Mode


802.11be EHT80 FullRU

Plot on 5985 MHz




10:29:33 PM 05/05/2026

Plot on 6225 MHz




10:25:27 PM 04/30/2026

Plot on 6385 MHz



10:38:13 PM 05/05/2026


Plot on 6465 MHz



11:02:23 PM 04/30/2026




Plot on 6625 MHz




11:07:02 PM 05/05/2026

Plot on 6705 MHz




11:54:11 PM 04/30/2026

Plot on 6785 MHz



12:03:23 AM 05/05/2026


Plot on 6865 MHz



11:15:11 PM 05/05/2026




Plot on 6945 MHz




12:12:23 AM 05/01/2026

Plot on 7025 MHz



12:21:49 AM 05/01/2026

Plot on 6545 MHz




11:15:41 PM 04/30/2026



EUT Mode


802.11be EHT160 FullIRU

Plot on 6025 MHz




12:10:03 AM 05/06/2026

Plot on 6185 MHz




12:13:51 AM 04/30/2026

Plot on 6345 MHz



12:27:32 AM 05/06/2026


Plot on 6665 MHz



12:34:25 AM 04/30/2026




Plot on 6825 MHz




12:52:07 AM 04/30/2026

Plot on 6985 MHz



01:17:55 AM 04/30/2026

Plot on 6505 MHz




12:25:08 AM 04/30/2026



EUT Mode


802.11be EHT320 FullIRU

Plot on 6105 MHz




04:45:43 AM 05/03/2026

Plot on 6265 MHz




04:43:25 AM 05/03/2026

Plot on 6425 MHz



04:40:32 AM 05/03/2026

Plot on 6585 MHz



04:37:47 AM 05/03/2026