





Plot on 6745 MHz



04:35:09 AM 05/03/2026

Plot on 6905 MHz



04:32:16 AM 05/03/2026




MIMO <Ant. 1+2+3+4(Ant2)>

EUT Mode


802.11a

Plot on 5955 MHz




04:53:27 AM 05/02/2026

Plot on 6195 MHz




09:49:32 PM 05/02/2026

Plot on 6415 MHz



09:59:30 PM 05/02/2026


Plot on 6435 MHz



10:35:21 PM 05/02/2026




Plot on 6475 MHz




10:50:36 PM 05/02/2026

Plot on 6515 MHz




10:57:27 PM 05/02/2026

Plot on 6535 MHz



11:07:01 PM 05/02/2026


Plot on 6695 MHz



11:15:22 PM 05/02/2026




Plot on 6855 MHz




11:22:01 PM 05/02/2026

Plot on 6875 MHz




11:59:04 PM 05/02/2026

Plot on 6895 MHz



12:08:31 AM 05/03/2026


Plot on 6995 MHz



12:19:47 AM 05/03/2026



Plot on 7095 MHz






EUT Mode


802.11be EHT20 FullRU

Plot on 5955 MHz




11:39:24 PM 05/04/2026

Plot on 6195 MHz




08:42:45 PM 04/29/2026

Plot on 6415 MHz



11:51:30 PM 05/04/2026


Plot on 6435 MHz



11:59:06 PM 05/04/2026




Plot on 6475 MHz




08:57:47 PM 04/29/2026

Plot on 6515 MHz




12:27:28 AM 05/05/2026

Plot on 6535 MHz



12:36:08 AM 05/05/2026


Plot on 6695 MHz



09:28:38 PM 04/29/2026




Plot on 6855 MHz




09:37:59 PM 04/29/2026

Plot on 6875 MHz




12:51:15 AM 05/05/2026

Plot on 6895 MHz



01:18:12 AM 05/05/2026


Plot on 6995 MHz



09:53:58 PM 04/29/2026



Plot on 7095 MHz






EUT Mode


802.11be EHT40 FullIRU

Plot on 5965 MHz




01:36:52 AM 05/05/2026

Plot on 6205 MHz




01:32:47 PM 04/30/2026

Plot on 6405 MHz



07:38:26 PM 05/05/2026


Plot on 6445 MHz



08:13:26 PM 05/05/2026




Plot on 6485 MHz




07:42:56 PM 04/30/2026

Plot on 6565 MHz




08:31:36 PM 05/05/2026

Plot on 6685 MHz



08:15:43 PM 04/30/2026


Plot on 6845 MHz



08:56:50 PM 04/30/2026




Plot on 6885 MHz




08:39:19 PM 05/05/2026

Plot on 6925 MHz




08:46:24 PM 05/05/2026

Plot on 7005 MHz



09:09:39 PM 04/30/2026


Plot on 7085 MHz



08:57:19 PM 05/05/2026



Plot on 6525 MHz






EUT Mode


802.11be EHT80 FullRU

Plot on 5985 MHz




09:28:35 PM 05/05/2026

Plot on 6225 MHz




09:24:26 PM 04/30/2026

Plot on 6385 MHz



09:37:15 PM 05/05/2026


Plot on 6465 MHz



10:01:23 PM 04/30/2026




Plot on 6625 MHz




10:06:04 PM 05/05/2026

Plot on 6705 MHz




10:53:10 PM 04/30/2026

Plot on 6785 MHz



11:02:21 PM 04/30/2026


Plot on 6865 MHz



10:14:13 PM 05/05/2026




Plot on 6945 MHz




11:11:22 PM 04/30/2026

Plot on 7025 MHz



11:20:50 PM 04/30/2026

Plot on 6545 MHz




10:14:41 PM 04/30/2026



EUT Mode


802.11be EHT160 FullIRU

Plot on 6025 MHz




11:09:07 PM 05/05/2026

Plot on 6185 MHz




11:12:51 PM 04/29/2026

Plot on 6345 MHz



11:26:36 PM 05/05/2026

Plot on 6665 MHz



11:33:24 PM 04/29/2026