





Plot on 6825 MHz




11:51:06 PM 04/29/2026

Plot on 6985 MHz



12:16:55 AM 04/30/2026

Plot on 6505 MHz




11:24:05 PM 04/29/2026



EUT Mode


802.11be EHT320 FullIRU

Plot on 6105 MHz




02:52:38 AM 05/03/2026

Plot on 6265 MHz




03:19:58 AM 05/03/2026

Plot on 6425 MHz



03:37:24 AM 05/03/2026


Plot on 6585 MHz



03:59:35 AM 05/03/2026




Plot on 6745 MHz



04:20:35 AM 05/03/2026

Plot on 6905 MHz



04:27:33 AM 05/03/2026




MIMO <Ant. 1+2+3+4(Ant3)>

EUT Mode


802.11a

Plot on 5955 MHz




06:25:13 AM 05/02/2026

Plot on 6195 MHz




11:21:15 PM 05/02/2026

Plot on 6415 MHz



11:31:13 PM 05/02/2026


Plot on 6435 MHz



12:07:06 AM 05/03/2026




Plot on 6475 MHz




12:22:19 AM 05/03/2026

Plot on 6515 MHz




12:29:12 AM 05/03/2026

Plot on 6535 MHz



12:38:45 AM 05/03/2026


Plot on 6695 MHz



12:47:05 AM 05/03/2026




Plot on 6855 MHz




12:53:44 AM 05/03/2026

Plot on 6875 MHz




01:30:47 AM 05/03/2026

Plot on 6895 MHz



01:40:14 AM 05/03/2026


Plot on 6995 MHz



01:51:30 AM 05/03/2026



Plot on 7095 MHz






EUT Mode


802.11be EHT20 FullIRU

Plot on 5955 MHz




01:11:09 AM 05/05/2026

Plot on 6195 MHz




10:14:31 PM 04/29/2026

Plot on 6415 MHz



01:23:12 AM 05/05/2026


Plot on 6435 MHz



01:30:50 AM 05/05/2026




Plot on 6475 MHz




10:29:35 PM 04/29/2026

Plot on 6515 MHz




01:59:14 AM 05/05/2026

Plot on 6535 MHz



02:07:52 AM 05/05/2026


Plot on 6695 MHz



11:00:23 PM 04/29/2026




Plot on 6855 MHz




11:09:46 PM 04/29/2026

Plot on 6875 MHz




02:22:58 AM 05/05/2026

Plot on 6895 MHz



02:49:55 AM 05/05/2026


Plot on 6995 MHz



11:25:45 PM 04/29/2026



Plot on 7095 MHz






EUT Mode


802.11be EHT40 FullIRU

Plot on 5965 MHz




03:08:34 AM 05/05/2026

Plot on 6205 MHz




09:04:33 PM 04/30/2026

Plot on 6405 MHz



09:10:09 PM 05/05/2026


Plot on 6445 MHz



09:45:08 PM 05/05/2026




Plot on 6485 MHz




09:14:42 PM 04/30/2026

Plot on 6565 MHz




10:03:18 PM 05/05/2026

Plot on 6685 MHz



09:47:28 PM 04/30/2026


Plot on 6845 MHz



10:28:36 PM 04/30/2026




Plot on 6885 MHz




10:11:01 PM 05/05/2026

Plot on 6925 MHz




10:18:08 PM 05/05/2026

Plot on 7005 MHz



10:41:24 PM 04/30/2026


Plot on 7085 MHz



10:29:03 PM 05/05/2026



Plot on 6525 MHz






EUT Mode


802.11be EHT80 FullRU

Plot on 5985 MHz




11:00:18 PM 05/05/2026

Plot on 6225 MHz




10:56:13 PM 04/30/2026

Plot on 6385 MHz



11:09:00 PM 05/05/2026


Plot on 6465 MHz



11:33:09 PM 04/30/2026




Plot on 6625 MHz




11:37:47 PM 05/05/2026

Plot on 6705 MHz




12:24:56 AM 05/01/2026

Plot on 6785 MHz



12:34:07 AM 05/01/2026

Plot on 6865 MHz



11:46:57 PM 05/05/2026