





Plot on 6945 MHz




12:43:07 AM 05/01/2026

Plot on 7025 MHz



12:52:34 AM 05/01/2026

Plot on 6545 MHz




11:46:28 PM 04/30/2026



EUT Mode


802.11be EHT160 FullIRU

Plot on 6025 MHz




12:40:48 AM 05/06/2026

Plot on 6185 MHz




12:44:37 AM 04/30/2026

Plot on 6345 MHz



12:58:18 AM 05/06/2026


Plot on 6665 MHz




01:05:12 AM 04/30/2026




Plot on 6825 MHz



Plot on 6985 MHz



Plot on 6505 MHz






EUT Mode


802.11be EHT320 FullIRU

Plot on 6105 MHz




04:24:22 AM 05/03/2026

Plot on 6265 MHz




04:51:41 AM 05/03/2026

Plot on 6425 MHz



05:09:10 AM 05/03/2026


Plot on 6585 MHz



05:31:18 AM 05/03/2026




Plot on 6745 MHz



05:52:18 AM 05/03/2026

Plot on 6905 MHz



05:59:16 AM 05/03/2026




MIMO <Ant. 1+2+3+4(Ant4)>

EUT Mode


802.11a

Plot on 5955 MHz




05:00:12 AM 05/02/2026

Plot on 6195 MHz




09:56:12 PM 05/02/2026

Plot on 6415 MHz



10:06:10 PM 05/02/2026


Plot on 6435 MHz



10:42:04 PM 05/02/2026




Plot on 6475 MHz




10:57:16 PM 05/02/2026

Plot on 6515 MHz




11:04:10 PM 05/02/2026

Plot on 6535 MHz



11:13:41 PM 05/02/2026


Plot on 6695 MHz



11:22:02 PM 05/02/2026




Plot on 6855 MHz




11:28:41 PM 05/02/2026

Plot on 6875 MHz




12:05:44 AM 05/03/2026

Plot on 6895 MHz



12:15:11 AM 05/03/2026


Plot on 6995 MHz



12:26:27 AM 05/03/2026



Plot on 7095 MHz






EUT Mode


802.11be EHT20 FullIRU

Plot on 5955 MHz




11:46:04 PM 05/04/2026

Plot on 6195 MHz




08:49:25 PM 04/29/2026

Plot on 6415 MHz



11:58:11 PM 05/04/2026


Plot on 6435 MHz



12:05:48 AM 05/05/2026




Plot on 6475 MHz




09:04:31 PM 04/29/2026

Plot on 6515 MHz




12:34:08 AM 05/05/2026

Plot on 6535 MHz



12:42:49 AM 05/05/2026


Plot on 6695 MHz



09:35:21 PM 04/29/2026




Plot on 6855 MHz




09:44:44 PM 04/29/2026

Plot on 6875 MHz




12:57:54 AM 05/05/2026

Plot on 6895 MHz



01:24:51 AM 05/05/2026


Plot on 6995 MHz



10:00:44 PM 04/29/2026



Plot on 7095 MHz






EUT Mode


802.11be EHT40 FullRU

Plot on 5965 MHz




01:43:31 AM 05/05/2026

Plot on 6205 MHz




07:39:26 PM 04/30/2026

Plot on 6405 MHz



07:45:03 PM 05/05/2026


Plot on 6445 MHz



08:20:05 PM 05/05/2026




Plot on 6485 MHz




07:49:39 PM 04/30/2026

Plot on 6565 MHz




08:38:15 PM 05/05/2026

Plot on 6685 MHz



08:22:16 PM 04/30/2026


Plot on 6845 MHz



09:03:32 PM 04/30/2026




Plot on 6885 MHz




08:45:58 PM 05/05/2026

Plot on 6925 MHz




08:53:05 PM 05/05/2026

Plot on 7005 MHz



09:16:22 PM 04/30/2026

Plot on 7085 MHz



09:04:01 PM 05/05/2026



Plot on 6525 MHz

