





EUT Mode

802.11be EHT320 Puncture80 2


Plot on 6105 MHz




Plot on 6425 MHz



Plot on 6585 MHz



Plot on 6905 MHz







EUT Mode

802.11be EHT320 Puncture80 4


Plot on 6105 MHz




Plot on 6425 MHz



Plot on 6585 MHz



Plot on 6905 MHz







EUT Mode

802.11be EHT320 Puncture120 1


Plot on 6105 MHz




Plot on 6425 MHz



Plot on 6585 MHz



Plot on 6905 MHz







EUT Mode

802.11be EHT320 Puncture120 6


Plot on 6105 MHz




Plot on 6425 MHz



Plot on 6585 MHz



Plot on 6905 MHz






EUT Mode


802.11be EHT320 Puncture120 7

Plot on 6105 MHz




05:22:31 PM 09/05/2025

Plot on 6425 MHz




11:59:36 AM 09/12/2025

Plot on 6585 MHz



04:08:00 PM 09/12/2025

Plot on 6905 MHz




10:01:10 AM 09/15/2025




EUT Mode

802.11be EHT320 Puncture120 12


Plot on 6105 MHz




Plot on 6425 MHz



Plot on 6585 MHz



Plot on 6905 MHz






MIMO <Ant. 4+3+2+1(2)>


EUT Mode

802.11be EHT320 Puncture40 1


Plot on 6105 MHz




Plot on 6425 MHz



Plot on 6585 MHz



Plot on 6905 MHz







EUT Mode

802.11be EHT320 Puncture40 4


Plot on 6105 MHz




Plot on 6425 MHz



Plot on 6585 MHz



Plot on 6905 MHz






EUT Mode


802.11be EHT320 Puncture40 8

Plot on 6105 MHz




02:14:33 PM 09/05/2025

Plot on 6425 MHz




10:38:16 AM 09/12/2025

Plot on 6585 MHz



02:40:51 PM 09/12/2025

Plot on 6905 MHz




05:11:00 PM 09/12/2025




EUT Mode

802.11be EHT320 Puncture80 1


Plot on 6105 MHz




Plot on 6425 MHz



Plot on 6585 MHz



Plot on 6905 MHz







EUT Mode

802.11be EHT320 Puncture80 2


Plot on 6105 MHz




Plot on 6425 MHz



Plot on 6585 MHz



Plot on 6905 MHz







EUT Mode

802.11be EHT320 Puncture80 4


Plot on 6105 MHz




Plot on 6425 MHz



Plot on 6585 MHz



Plot on 6905 MHz






EUT Mode


802.11be EHT320 Puncture120 1

Plot on 6105 MHz




04:57:41 PM 09/05/2025

Plot on 6425 MHz




11:36:55 AM 09/12/2025

Plot on 6585 MHz



03:35:00 PM 09/12/2025

Plot on 6905 MHz




05:44:28 PM 09/12/2025




EUT Mode

802.11be EHT320 Puncture120 6


Plot on 6105 MHz



Plot on 6425 MHz



Plot on 6585 MHz



Plot on 6905 MHz

