





EUT Mode

802.11be EHT160 Puncture20 8


Plot on 6025 MHz




Plot on 6505 MHz



Plot on 6665 MHz



Plot on 6985 MHz






EUT Mode


802.11be EHT160 Puncture40 1

Plot on 6025 MHz




12:24:35 PM 09/04/2025

Plot on 6505 MHz




03:15:34 PM 09/04/2025

Plot on 6665 MHz



04:01:38 PM 09/04/2025

Plot on 6985 MHz




05:00:23 PM 09/04/2025



EUT Mode


802.11be EHT160 Puncture40 2

Plot on 6025 MHz




02:06:29 PM 09/04/2025

Plot on 6505 MHz




03:22:03 PM 09/04/2025

Plot on 6665 MHz



04:09:04 PM 09/04/2025

Plot on 6985 MHz




05:11:50 PM 09/04/2025



EUT Mode


802.11be EHT160 Puncture40 4

Plot on 6025 MHz




02:24:26 PM 09/04/2025

Plot on 6505 MHz




03:31:09 PM 09/04/2025

Plot on 6665 MHz



04:15:52 PM 09/04/2025

Plot on 6985 MHz



05:18:35 PM 09/04/2025




MIMO <Ant. 4+3+2+1(3)>

EUT Mode


802.11be EHT160 Puncture20 1

Plot on 6025 MHz




11:39:49 AM 09/04/2025

Plot on 6505 MHz




02:39:00 PM 09/04/2025

Plot on 6665 MHz



03:40:58 PM 09/04/2025

Plot on 6985 MHz




04:42:28 PM 09/04/2025



EUT Mode


802.11be EHT160 Puncture20 4

Plot on 6025 MHz




11:47:25 AM 09/04/2025

Plot on 6505 MHz




02:48:15 PM 09/04/2025

Plot on 6665 MHz



03:47:44 PM 09/04/2025

Plot on 6985 MHz




04:48:41 PM 09/04/2025




EUT Mode

802.11be EHT160 Puncture20 8


Plot on 6025 MHz




Plot on 6505 MHz



Plot on 6665 MHz



Plot on 6985 MHz







EUT Mode

802.11be EHT160 Puncture40 1


Plot on 6025 MHz




Plot on 6505 MHz



Plot on 6665 MHz



Plot on 6985 MHz







EUT Mode

802.11be EHT160 Puncture40 2


Plot on 6025 MHz




Plot on 6505 MHz



Plot on 6665 MHz



Plot on 6985 MHz






EUT Mode


802.11be EHT160 Puncture40 4

Plot on 6025 MHz




02:26:17 PM 09/04/2025

Plot on 6505 MHz




03:32:31 PM 09/04/2025

Plot on 6665 MHz



04:17:05 PM 09/04/2025

Plot on 6985 MHz



05:19:44 PM 09/04/2025




MIMO <Ant. 4+3+2+1(2)>

EUT Mode


802.11be EHT160 Puncture20 1

Plot on 6025 MHz




11:41:30 AM 09/04/2025

Plot on 6505 MHz




02:40:38 PM 09/04/2025

Plot on 6665 MHz



03:42:26 PM 09/04/2025

Plot on 6985 MHz




04:43:47 PM 09/04/2025




EUT Mode

802.11be EHT160 Puncture20 4


Plot on 6025 MHz




Plot on 6505 MHz



Plot on 6665 MHz



Plot on 6985 MHz







EUT Mode

802.11be EHT160 Puncture20 8


Plot on 6025 MHz




Plot on 6505 MHz



Plot on 6665 MHz



Plot on 6985 MHz






EUT Mode


802.11be EHT160 Puncture40 1

Plot on 6025 MHz




12:29:00 PM 09/04/2025

Plot on 6505 MHz




03:18:25 PM 09/04/2025

Plot on 6665 MHz



04:05:14 PM 09/04/2025

Plot on 6985 MHz



05:03:24 PM 09/04/2025