





EUT Mode

802.11be EHT160 Puncture40 2


Plot on 6025 MHz




Plot on 6505 MHz



Plot on 6665 MHz



Plot on 6985 MHz







EUT Mode

802.11be EHT160 Puncture40 4


Plot on 6025 MHz




Plot on 6505 MHz



Plot on 6665 MHz



Plot on 6985 MHz






MIMO <Ant. 4+3+2+1(1)>


EUT Mode

802.11be EHT160 Puncture20 1


Plot on 6025 MHz




Plot on 6505 MHz



Plot on 6665 MHz



Plot on 6985 MHz







EUT Mode

802.11be EHT160 Puncture20 4


Plot on 6025 MHz




Plot on 6505 MHz



Plot on 6665 MHz



Plot on 6985 MHz







EUT Mode

802.11be EHT160 Puncture20 8


Plot on 6025 MHz




Plot on 6505 MHz



Plot on 6665 MHz



Plot on 6985 MHz






EUT Mode


802.11be EHT160 Puncture40 1

Plot on 6025 MHz




12:30:32 PM 09/04/2025

Plot on 6505 MHz




03:19:34 PM 09/04/2025

Plot on 6665 MHz



04:06:39 PM 09/04/2025

Plot on 6985 MHz




05:04:30 PM 09/04/2025




EUT Mode

802.11be EHT160 Puncture40 2


Plot on 6025 MHz




Plot on 6505 MHz



Plot on 6665 MHz



Plot on 6985 MHz







EUT Mode

802.11be EHT160 Puncture40 4


Plot on 6025 MHz




Plot on 6505 MHz



Plot on 6665 MHz



Plot on 6985 MHz






MIMO <Ant. 4+3+2+1(4)>

EUT Mode


802.11be EHT320 Puncture40 1

Plot on 6105 MHz




12:11:04 PM 09/05/2025

Plot on 6425 MHz




10:10:31 AM 09/12/2025

Plot on 6585 MHz



02:20:34 PM 09/12/2025

Plot on 6905 MHz




04:38:35 PM 09/12/2025



EUT Mode


802.11be EHT320 Puncture40 4

Plot on 6105 MHz




12:25:22 PM 09/05/2025

Plot on 6425 MHz




10:21:21 AM 09/12/2025

Plot on 6585 MHz



02:29:23 PM 09/12/2025

Plot on 6905 MHz




05:00:06 PM 09/12/2025




EUT Mode

802.11be EHT320 Puncture40 8


Plot on 6105 MHz




Plot on 6425 MHz



Plot on 6585 MHz



Plot on 6905 MHz







EUT Mode

802.11be EHT320 Puncture80 1


Plot on 6105 MHz




Plot on 6425 MHz



Plot on 6585 MHz



Plot on 6905 MHz







EUT Mode

802.11be EHT320 Puncture80 2


Plot on 6105 MHz




Plot on 6425 MHz



Plot on 6585 MHz



Plot on 6905 MHz







EUT Mode

802.11be EHT320 Puncture80 4


Plot on 6105 MHz



Plot on 6425 MHz



Plot on 6585 MHz



Plot on 6905 MHz

