





EUT Mode

802.11be EHT320 Puncture120 1


Plot on 6105 MHz




Plot on 6425 MHz



Plot on 6585 MHz



Plot on 6905 MHz







EUT Mode

802.11be EHT320 Puncture120 6


Plot on 6105 MHz




Plot on 6425 MHz



Plot on 6585 MHz



Plot on 6905 MHz







EUT Mode

802.11be EHT320 Puncture120 7


Plot on 6105 MHz




Plot on 6425 MHz



Plot on 6585 MHz



Plot on 6905 MHz






EUT Mode


802.11be EHT320 Puncture120 12

Plot on 6105 MHz




05:30:40 PM 09/05/2025

Plot on 6425 MHz




12:11:39 PM 09/12/2025

Plot on 6585 MHz



04:24:26 PM 09/12/2025

Plot on 6905 MHz



10:42:29 AM 09/15/2025




MIMO <Ant. 4+3+2+1(3)>

EUT Mode


802.11be EHT320 Puncture40 1

Plot on 6105 MHz




12:14:08 PM 09/05/2025

Plot on 6425 MHz




10:13:27 AM 09/12/2025

Plot on 6585 MHz



02:22:04 PM 09/12/2025

Plot on 6905 MHz




04:41:19 PM 09/12/2025




EUT Mode

802.11be EHT320 Puncture40 4


Plot on 6105 MHz




Plot on 6425 MHz



Plot on 6585 MHz



Plot on 6905 MHz







EUT Mode

802.11be EHT320 Puncture40 8


Plot on 6105 MHz




Plot on 6425 MHz



Plot on 6585 MHz



Plot on 6905 MHz







EUT Mode

802.11be EHT320 Puncture80 1


Plot on 6105 MHz




Plot on 6425 MHz



Plot on 6585 MHz



Plot on 6905 MHz







EUT Mode

802.11be EHT320 Puncture80 2


Plot on 6105 MHz




Plot on 6425 MHz



Plot on 6585 MHz



Plot on 6905 MHz







EUT Mode

802.11be EHT320 Puncture80 4


Plot on 6105 MHz




Plot on 6425 MHz



Plot on 6585 MHz



Plot on 6905 MHz







EUT Mode

802.11be EHT320 Puncture120 1


Plot on 6105 MHz




Plot on 6425 MHz



Plot on 6585 MHz



Plot on 6905 MHz






EUT Mode


802.11be EHT320 Puncture120 6

Plot on 6105 MHz




05:09:07 PM 09/05/2025

Plot on 6425 MHz




11:46:29 AM 09/12/2025

Plot on 6585 MHz



03:40:42 PM 09/12/2025

Plot on 6905 MHz




05:49:35 PM 09/12/2025




EUT Mode

802.11be EHT320 Puncture120 7


Plot on 6105 MHz




Plot on 6425 MHz



Plot on 6585 MHz



Plot on 6905 MHz







EUT Mode

802.11be EHT320 Puncture120 12


Plot on 6105 MHz



Plot on 6425 MHz



Plot on 6585 MHz



Plot on 6905 MHz

