




EUT Mode


802.11be EHT80 Puncture20 4

Plot on 5985 MHz




04:40:56 PM 09/03/2025

Plot on 6465 MHz




05:09:34 PM 09/03/2025

Plot on 6705 MHz



05:33:02 PM 09/03/2025

Plot on 7025 MHz



05:57:07 PM 09/03/2025




MIMO <Ant. 4+3+2+1(1)>


EUT Mode

802.11be EHT80 Puncture20 1


Plot on 5985 MHz




Plot on 6465 MHz



Plot on 6705 MHz



Plot on 7025 MHz






EUT Mode


802.11be EHT80 Puncture20 2

Plot on 5985 MHz




04:23:09 PM 09/03/2025

Plot on 6465 MHz




05:03:55 PM 09/03/2025

Plot on 6705 MHz



05:24:44 PM 09/03/2025

Plot on 7025 MHz




05:52:58 PM 09/03/2025




EUT Mode

802.11be EHT80 Puncture20 4


Plot on 5985 MHz




Plot on 6465 MHz



Plot on 6705 MHz



Plot on 7025 MHz






MIMO <Ant. 4+3+2+1(4)>

EUT Mode


802.11be EHT160 Puncture20 1

Plot on 6025 MHz




11:38:41 AM 09/04/2025

Plot on 6505 MHz




02:37:40 PM 09/04/2025

Plot on 6665 MHz



03:40:00 PM 09/04/2025

Plot on 6985 MHz




04:38:08 PM 09/04/2025




EUT Mode

802.11be EHT160 Puncture20 4


Plot on 6025 MHz




Plot on 6505 MHz



Plot on 6665 MHz



Plot on 6985 MHz







EUT Mode

802.11be EHT160 Puncture20 8


Plot on 6025 MHz




Plot on 6505 MHz



Plot on 6665 MHz



Plot on 6985 MHz






EUT Mode


802.11be EHT160 Puncture40 1

Plot on 6025 MHz




12:24:35 PM 09/04/2025

Plot on 6505 MHz




03:15:34 PM 09/04/2025

Plot on 6665 MHz



04:01:38 PM 09/04/2025

Plot on 6985 MHz




05:00:23 PM 09/04/2025




EUT Mode

802.11be EHT160 Puncture40 2


Plot on 6025 MHz




Plot on 6505 MHz



Plot on 6665 MHz



Plot on 6985 MHz







EUT Mode

802.11be EHT160 Puncture40 4


Plot on 6025 MHz




Plot on 6505 MHz



Plot on 6665 MHz



Plot on 6985 MHz






MIMO <Ant. 4+3+2+1(3)>

EUT Mode


802.11be EHT160 Puncture20 1

Plot on 6025 MHz




11:39:49 AM 09/04/2025

Plot on 6505 MHz




02:39:00 PM 09/04/2025

Plot on 6665 MHz



03:40:58 PM 09/04/2025

Plot on 6985 MHz




04:42:28 PM 09/04/2025




EUT Mode

802.11be EHT160 Puncture20 4


Plot on 6025 MHz




Plot on 6505 MHz



Plot on 6665 MHz



Plot on 6985 MHz






EUT Mode


802.11be EHT160 Puncture20 8

Plot on 6025 MHz




12:02:42 PM 09/04/2025

Plot on 6505 MHz




02:54:47 PM 09/04/2025

Plot on 6665 MHz



03:54:02 PM 09/04/2025

Plot on 6985 MHz




04:55:17 PM 09/04/2025



EUT Mode


802.11be EHT160 Puncture40 1

Plot on 6025 MHz




12:27:54 PM 09/04/2025

Plot on 6505 MHz




03:16:55 PM 09/04/2025

Plot on 6665 MHz



04:02:47 PM 09/04/2025

Plot on 6985 MHz



05:02:33 PM 09/04/2025