





EUT Mode

802.11be EHT160 Puncture40 2


Plot on 6025 MHz




Plot on 6505 MHz



Plot on 6665 MHz



Plot on 6985 MHz






EUT Mode


802.11be EHT160 Puncture40 4

Plot on 6025 MHz




02:26:17 PM 09/04/2025

Plot on 6505 MHz




03:32:31 PM 09/04/2025

Plot on 6665 MHz



04:17:05 PM 09/04/2025

Plot on 6985 MHz



05:19:44 PM 09/04/2025




MIMO <Ant. 4+3+2+1(2)>

EUT Mode


802.11be EHT160 Puncture20 1

Plot on 6025 MHz




11:41:30 AM 09/04/2025

Plot on 6505 MHz




02:40:38 PM 09/04/2025

Plot on 6665 MHz



03:42:26 PM 09/04/2025

Plot on 6985 MHz




04:43:47 PM 09/04/2025



EUT Mode


802.11be EHT160 Puncture20 4

Plot on 6025 MHz




11:48:30 AM 09/04/2025

Plot on 6505 MHz




02:49:09 PM 09/04/2025

Plot on 6665 MHz



03:49:42 PM 09/04/2025

Plot on 6985 MHz




04:49:42 PM 09/04/2025




EUT Mode

802.11be EHT160 Puncture20 8


Plot on 6025 MHz




Plot on 6505 MHz



Plot on 6665 MHz



Plot on 6985 MHz






EUT Mode


802.11be EHT160 Puncture40 1

Plot on 6025 MHz




12:29:00 PM 09/04/2025

Plot on 6505 MHz




03:18:25 PM 09/04/2025

Plot on 6665 MHz



04:05:14 PM 09/04/2025

Plot on 6985 MHz




05:03:24 PM 09/04/2025




EUT Mode

802.11be EHT160 Puncture40 2


Plot on 6025 MHz




Plot on 6505 MHz



Plot on 6665 MHz



Plot on 6985 MHz







EUT Mode

802.11be EHT160 Puncture40 4


Plot on 6025 MHz




Plot on 6505 MHz



Plot on 6665 MHz



Plot on 6985 MHz






MIMO <Ant. 4+3+2+1(1)>

EUT Mode


802.11be EHT160 Puncture20 1

Plot on 6025 MHz




11:42:47 AM 09/04/2025

Plot on 6505 MHz




02:43:25 PM 09/04/2025

Plot on 6665 MHz



03:43:44 PM 09/04/2025

Plot on 6985 MHz




04:45:11 PM 09/04/2025



EUT Mode


802.11be EHT160 Puncture20 4

Plot on 6025 MHz




11:49:50 AM 09/04/2025

Plot on 6505 MHz




02:50:21 PM 09/04/2025

Plot on 6665 MHz



03:50:48 PM 09/04/2025

Plot on 6985 MHz




04:50:44 PM 09/04/2025




EUT Mode

802.11be EHT160 Puncture20 8


Plot on 6025 MHz




Plot on 6505 MHz



Plot on 6665 MHz



Plot on 6985 MHz







EUT Mode

802.11be EHT160 Puncture40 1


Plot on 6025 MHz




Plot on 6505 MHz



Plot on 6665 MHz



Plot on 6985 MHz







EUT Mode

802.11be EHT160 Puncture40 2


Plot on 6025 MHz




Plot on 6505 MHz



Plot on 6665 MHz



Plot on 6985 MHz







EUT Mode

802.11be EHT160 Puncture40 4


Plot on 6025 MHz



Plot on 6505 MHz



Plot on 6665 MHz



Plot on 6985 MHz

