

Marstech

From: "Baniqued Boni" <boni@cct.com.hk>
To: "Linda (E-mail)" <marstech@look.ca>
Cc: "Fung Cheuk Chiu, Johnny" <johnnyfung@cct.com.hk>; "Lee Wai Sheung, Tony" <tonylee@cct.com.hk>
Sent: July 25, 2003 8:37 AM
Attach: 25830A RF Schematics - 1.pdf; 21095A RF Schematics.pdf
Subject: Models 25830XXX-A and 21095XXX-A Part 15 Modifications

Dear Linda,

Below are the modifications for 25830A and 21095A Part 15 spurious emissions problem.

Model 25830A:

Handset RF Module

- 1) Add 1nF capacitor @ PA_EN terminal
- 2) Add 1nF capacitor @ TX_EN terminal
- 3) Change C37 from 22p to 15p

Model 21095XXX-A:

Handset RF Module

- 1) Add 1nF capacitor @ TX_EN terminal
- 2) Change C37 from 22p to 15p

See attached copy of revised RF schematics of the above models for your reference.

Best Regards,

Boni

<<25830A RF Schematics - 1.pdf>> <<21095A RF Schematics.pdf>>