

TIMCO ENGINEERING INC.
849 NW State Road 45
Newberry, Florida 32669
888.472.2424 F 352.472.2030 email: sid@timcoengr.com

3/7/00

Mr. Andy Leimer
FCC

SUBJECT: Thompson Consumer Electronics Inc. FCCID: G9H26920B

REFERENCE: EA96825

The changes to this unit were as follows;

1. Back to back diodes D2, KDS226, were added across the antenna connection point to prevent overload of the receiver.
2. The D1 was added in series to the BUSY line.
3. The photographs were to show the changes to the printed circuit board to add these diodes.

We did not send a test report because we were not sure that retesting was required. If you require for us to retest the radiated emissions please let us know.

Best Regards,

Sid Sanders