







End view showing the MS Power/Communications Connector




Internal view, the "digital" PCA is visible




Internal view, showing Digital PCA & Other half of housing removed




Close-up of the Digital PCA




Digital PCA removed from the unit




RF PCA is now visible in the housing . (The Digital PCA was mounted above the RF PCA)




Close-Up of the RF PCA in the housing with the shields in place



RF PCA in housing with the shields removed



Close-Up of the RF PCA removed from the housing



Empty housing with both Digital and RF PCA's removed