



HERMON LABORATORIES

May 23, 2006

American TCB
6731 Whittier Ave
Suite C110
McLean, VA 22101
Attn: Mr. T. Johnson, Examining Engineer

RE: your e-mail dated May 4, 2006; Visonic Ltd.
FCC ID:GSA-ETC00433, ATCB003412

Dear Mr. Johnson,
Please find below the answers to your questions.

- 1) The revised Confidentiality_letter_16644_rev1 was uploaded on May 23, 2006 via Additional Information folder.
- 2) The Label_location_16644_rev1 with actual label sample in the frame was uploaded on May 23, 2006.
- 3) The revised test report VISRAD_FCC.16644_rev1 with corrected Table 7.1.1 was uploaded on May 23, 2006 .
- 4) Plot 7.2.18 was changed for correct one, refer to VISRAD_FCC.16644_rev1. The corrected User_Manual_16644_rev1_page1/page2 was uploaded on May 23, 2006.
- 5) The User Manual was corrected.
- 6) Please refer to plot 7.1.5 in the revised test report VISRAD_FCC.16644_rev1.
- 7) NA
- 8) The Tx pulse duration is the same for each mode of operation and the duty cycle factor is the same.
- 9) The file "Setup_photos_16644_rev1" with added photographs at OATS was uploaded on May 23, 2006.
- 10) We suppose – NA.

Thank you.

Marina Cherniavsky,

certification engineer
Hermon Laboratories