



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

October 15, 2002

RE: Visonic Ltd.

FCC ID: GSAK980MCW

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) Please provide external photographs of the back of the unit.
- 2) Please provide close up internal photographs of the top and bottom of each independent board.
- 3) The information given in the application states that the unit transmits once per hour to indicate transmitter status for supervisory purposes. As given in 15.231(a)(3) this is only allowed to determine system integrity for applications involving security or safety application ONLY. However, this transmission must be less than 1 second. Please provide information as to how long a single supervisory transmission takes.
- 4) This application did not include a request for confidentiality. Please confirm that confidentiality is not requested on this application.
- 5) It appears that the transmitter is contained on a separate board. Please provide the schematic for the TX board. Alternatively, if this board is purchased as an OEM part, please provide a parts list that shows this.
- 6) Please set the device to transmit normally and provide a plot of 10 seconds showing that once the device is triggered, it automatically stops transmitting in less than 5 seconds.
- 7) Please note that 1574.98, 2204.8, and 2834.82 MHz fall in restricted bands and are subject to 74 dBuV peak and 54 dBuV Avg limits.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.