



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

March 15, 2005

RE: Visonic Ltd.

FCC ID: GSAMCTIIR252

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) Although Message cycle and repeat cycling (switches 2 & 3, plus 4 & 5) may be acceptable during emergencies of life, the assist mode and user defined modes should not allow for message cycle and repeated message cycle modes. These modes are not considered acceptable under 15.231(a)(3/4). Please provide adequate information and tests to show compliance to these sections as necessary.
- 2) Supervisor TX appears to occur over 377 ms, while normal TX occur over 278 ms. Please provide information to support if this affects the worse case duty cycle used for average calculations.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.