



6.5. PHOTOGRAPHS OF RADIATED EMISSION TEST CONFIGURATION

PS/2 Mode

FRONT VIEW



REAR VIEW



FCC TEST REPORT


REPORT NO. : F892204

AT Mode

FRONT VIEW



REAR VIEW



SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

FCC ID : GYUR63SK

PAGE NUMBER : 25 OF 27

ISSUED DATE : Sep. 29, 1998


5.5. PHOTOGRAPHS OF CONDUCTED POWERLINE TEST CONFIGURATION

PS/2 Mode


FRONT VIEW



REAR VIEW



SIDE VIEW



SPORTON International Inc.

TEL : 886-2-2696-2488

FAX : 886-2-2696-2255

FCC ID : GYUR63SK

PAGE NUMBER : 16 OF 27

ISSUED DATE : Sep. 29, 1998

FCC TEST REPORT


REPORT NO. : F892204

AT Mode

FRONT VIEW



REAR VIEW



SPORTON International Inc.

TEL : 886-2-2696-2468

FAX : 886-2-2696-2255

FCC ID : GYUR63SK

PAGE NUMBER : 17 OF 27

ISSUED DATE : Sep. 29, 1998

SIDE VIEW

