

TAC/COM 2005 Tune-Up Procedure

There are no controls accessible to the user which could alter the intended functionality of the unit, or cause a condition that would allow the unit to operate out of the advertised specifications. Therefore, there is no applicable field tune-up procedure.