

SAMPLE

EXICOM

FCC ID: H4U-EX818283

MODEL No:EX8100 - 8200

Made in New Zealand by

EXICOM TECHNOLOGIES LTD

EXICOM

FCC ID: H4U-EX818283

MODEL No:EX8100 - 8200

Made in New Zealand by

EXICOM TECHNOLOGIES LTD

EXICOM

FCC ID: H4U-EX818283

MODEL No:EX8100 - 8200

Made in New Zealand by

EXICOM TECHNOLOGIES LTD

EXICOM

FCC ID: H4U-EX818283

MODEL No:EX8100 - 8200

Made in New Zealand by

EXICOM TECHNOLOGIES LTD

EXICOM

FCC ID: H4U-EX818283

MODEL No:EX8100 - 8200

Made in New Zealand by

EXICOM TECHNOLOGIES LTD

EXICOM

FCC ID: H4U-EX818283

MODEL No:EX8100 - 8200

Made in New Zealand by

EXICOM TECHNOLOGIES LTD



**Outer Label
Location Here**



100605



Industry
Canada

Industrie
Canada

Label here

This device complies with Part 15 and Part 68 of the FCC Rules.
Operation is subject to the two following conditions:

- (1) This device may not cause harmful interference, and
- (2) This device must accept any interference received, including interference that may cause undesired operations.

WIRE TO SUBSCRIBER SIDE

WARNING!

Remove battery before
shipping to avoid
excessive damage to the
unit.



STAHLIN
ENCLOSURES

DIVISION OF ROBROY INDUSTRIES
Belding, Michigan 48809
Phone (516) 794-0700

J1210HPL

