




CAUTION, STATIC SENSITIVE DEVICES
SERVICE AT STATIC FREE STATION.

ONE TRK SENSITIVE TYPE 2000
EX-2000
LAND MOUNT REPEATER



CONTROLLER TYPE 2932
HAWK
POINT TO POINT LINK



CAUTION, STATIC SENSITIVE DEVICES
SERVICE AT STATIC FREE STATION.

15 10'97

Exicom Technologies (1996) Limited
ID: H4U2950-2 CONTROLLER 2932



CONTROLLER TYPE 2932
HAWK
POINT TO POINT LINK