

Helen Zhao

Subject: FW: FW: ADVANCE SECURITY INC., FCC ID: H5OR43, Assessment NO.: AN04T4400, Notice#1

-----Original Message-----

From: feva@ccsemc.com.tw [mailto:feva@ccsemc.com.tw]

Sent: Tuesday, December 14, 2004 5:45 PM

To: Helen Zhao

Subject: Re: FW: ADVANCE SECURITY INC., FCC ID: H5OR43, Assessment NO.: AN04T4400, Notice#1

Dear Helen:

Question #1: FCC ID label format includes FCC DoC logo, which is not applicable in this case, please remove the FCC DoC logo from the label format.

--->Sorry about that!

Attached please find FCC ID LAB.pdf!

Question #2: The user manual does not contain warning statement(Information to the User) as specified in FCC 15.21. Please revise the user manual.

--->Sorry about that!

Attached please find User's Manual.pdf!

Question #3: The test report indicated that "The associated transmitter is manufactured by Advance Security Inc., FCC ID: H5OR43", but Form 731 indicated that the associated transmitter is FCC ID: H50T21. Please correct the report.

--->Sorry about that!

Attached please find Test Report.pdf!

Thank you very much for your information.

Best regards,

Eva Fan

12/14/2004