





FCC ID: H79DB-995

Reference modification letter: No.4


5



832006

FCC ID: H79DB-995


Reference modification letter: No.4,5



832006

FCC ID: H79DB-995

Reference modification letter: No.4,5




832006

FCC ID: H79DB-995
Reference modification letter: No.6




FCC ID: H79DB-995
Reference modification letter: No.7



832006

FCC ID: H79DB-995
Mechanical construction




832006

FCC ID: H79DB-995
Mechanical construction


FCC ID: H79DB-995
Mechanical construction

832006



832006

FCC ID: H79DB-995
Mechanical construction




832006




FCC ID: H79DB-995

Reference modification letter No.: 6,21



FCC ID: H79DB-995

Reference modification letter: No. 6, 8, 9, 10



FCC ID: H79DB-995
Mechanical construction

16

13


12

11

832006

FCC ID: H79DB-995

Reference modification letter: No. 11,12,13




FCC ID: H79DB-995

Reference modification letter: No.20



832006

FCC ID: H79DB-995
Mechanical construction



FCC ID: H79DB-995


Front side of main board & CRT board

FCC ID: H79DB-995

Reference modification letter: No.14,15,16

832006






832006

FCC ID: H79DB-995

Rear side of main board & CRT board

Reference modification letter: No. 17, 19


832006



FCC ID: H79DB-995

Reference modification letter: No.18



832006



FCC ID: H79DB-995


Mechanical construction

832006



FCC ID: H79DB-995
Mechanical construction




832006



FCC ID: H79DB-995

Front side of Function & Input board

832006



FCC ID: H79DB-995

Rear side of Function & Input board
Reference modification letter: No.17