



BABT
Claremont House, 34 Molesey Road
Walton on Thames
Surrey, KT12 4RQ
United Kingdom
Telephone: +44 (0)1932 251200
Fax: +44 (0)1932 251201

Ref: US/000050

13 November 2003

To FCC

Direct Dial: +44 (0)1932 251227
E-mail: Hilton.carr@babt.com
Website: www.tuvps.co.uk
www.babt.com

FCC id: H9P4111CDMA

Correction to Results Table in SAR report WS611456

The Test Laboratory have advised me of the following correction to the above test report.

This does not effect the particular compliance.

Replace the "System Performance/Validation Check results section on page 6 with the following:

1.3 TEST RESULT SUMMARY

SYSTEM PERFORMANCE / VALIDATION CHECK RESULTS

Prior to formal testing being performed, a System Check was performed in accordance with Appendix D IEEE1528 April 4th 2002 Draft Standard. The following results were obtained: -

Dipole Used	Frequency (MHz)	Max 1g SAR (W/kg)	Percentage Drift on 1g Reference	Max 10g SAR (W/kg)	Percentage Drift on 10g Reference
835	907.5	10.66*	-1.32%	6.94*	0.56%
1900	1883.6	36.99*	-2.92%	19.87*	0.35%
2450	2450.0	52.48*	0.15%	24.56*	2.33%

*Normalised to 1W

Yours sincerely

Hilton Carr
Task Manager, Certification and Technical Development
For TCB

