


Customer:
 Test Sample: 2.4 GHz Direct Sequence Spread Spectrum Transceiver
 Model No.: PPT4600 FCC ID: H0PPT4600XHW1W9
 Test Method: FCC 15.247 (a) Antenna Conducted Emissions 30 MHz to 25 GHz
 Notes: Center Frequency Tested: 2.402 GHz




Retif Testing Laboratories
 Report No. R-8392-1



Customer: Symbol Technologies
 Test Sample: 2.4 GHz Direct Sequence Spread Spectrum Transceiver
 Model No.: PPT4600 FCC ID: H06097460000HEW9
 Test Method: FCC 15.247 (e) Antenna Conducted Emissions 30 MHz to 25 GHz
 Notes: Center Frequency Tested: 2.462 GHz



Retif Testing Laboratories
 Report No. R-8392-1




Customer: Symbol Technologies
 Test Sample: 2.4 GHz Direct Sequence Spread Spectrum Transceiver
 Model No.: PPT4600 FCC ID: H11PPT4600041WVW
 Test Method: FCC 15.247 (c) Antenna Conducted Emissions 30 MHz to 25 GHz
 Notes: Center Frequency Tested: 2.462 GHz



Retif Testing Laboratories
 Report No. R-8392-1


R-8392-1 PPT4600 Antenna C.E. ND 2/2/00
 REF 2.5 dBm ATTN 10 dB



Customer: Symbol Technologies
 Test Sample: PPT4600
 Model No.: PPT4600
 Test Method: FCC ID: H01PPT-H00K0HWEW9
 Notes: FCC 15.247 (b) Antenna Conducted Emissions 30 kHz to 25 GHz
 Center Frequency Tested: 2.462 GHz



Retif Testing Laboratories
 Report No. R-8392-1




Customer: Symbol Technologies
 Test Sample: 2.4 GHz Direct Sequence Spread Spectrum Transceiver
 Model No.: PPT4600 FCC ID: H01PPT4600/1W9
 Test Method: FCC 15.247 (c) Antenna Conducted Emissions 30 MHz to 25 GHz
 Notes: Carrier Frequency Tested: 2.462 GHz

Date: February 4, 2000 Tech: N Diagram Sheet 35 of 45



Retif Testing Laboratories
 Report No. R-8392-1



Customer: Symbol Technologies
 Test Sample: 2.4 GHz Direct Sequence Spread Spectrum Transceiver
 Model No.: PPT4600 FCC ID: H388PPT40000HWEW9
 Test Method: FCC 15.247 (c) Antenna Conducted Emissions 30 MHz to 25 GHz
 Notes: Carrier Frequency Tested: 2.462 GHz

Date: February 4, 2000 Tech: N. Dragota Sheet: 36 of 45



Retif Testing Laboratories
 Report No. R-8392-1

