



WARNING • AVERTISSEMENT ADVERTENCIA

To avoid SERIOUS PERSONAL INJURY or DEATH:
• Disconnect ALL electric and battery power BEFORE performing ANY maintenance.
• After ANY adjustments are made, the safety reversal system MUST be tested. Door MUST reverse on contact with 1-1/2" high object (or 2x4 laid flat) on the floor. See instructions for proper adjustment procedure.

Pour prévenir d'éventuelles BLESSURES GRAVES, voire MORTELLES :

- Débrancher TOUTE alimentation électrique et la batterie AVANT d'effectuer TOUT entretien.
- Après avoir effectué QUELQUE réglage que ce soit, on DOIT faire l'essai du système d'inversion de sécurité. La porte de garage DOIT remonter au contact d'un objet d'une hauteur de 3,8 cm (1 1/2 po) (ou d'un 2 x 4 posé à plat) du sol. Voir les instructions pour la bonne méthode de réglage.

Para evitar una LESIÓN PERSONAL GRAVE o INCLUSO LA MUERTE:

- Desconecte TOTALMENTE la corriente eléctrica y de la batería ANTES de realizar CUALQUIER mantenimiento.
- Después de llevar a cabo CUALQUIER ajuste, SE DEBE probar el sistema de reversa de seguridad. La puerta DEBE retroceder al entrar en contacto con un objeto de 3,8 cm (1 1/2 de pulg.) de altura (o de 5 x 10 cm [2 x 4 pulg.] acostado en el piso). Consulte las instrucciones para conocer el procedimiento de ajuste adecuado.

RESIDENTIAL DOOR OPENER
OPÉRATEUR DE PORTE RESIDENCIAL
OPERADOR DE PUERTA RESIDENCIAL

Strip wires to:  7/16"

NEC CL2 12V ACTUAL SIZE



Patents / Brevets / Patentes
See / Voir / Ver: www.chamberlaingroup.com/patents

THE CHAMBERLAIN GROUP, INC. USA
Country of origin: Mexico / Pays d'origine: Mexique
País de origen: México

myQ SERIAL NUMBER/NÚMERO DE SERIE DE myQ/NUMÉRO DE SÉRIE DE myQ

MAC ADDRESS / ADRESSE MAC / DIRECCIÓN MAC

PART/PIÈCE /PART:

DATE / FECHA:

FCC ID: HBW0454X6

IC: 2666A 2666A-0454X6

Contains:

FCC ID: HBWGD0CAMF1

IC: 2666A-GD0CAMF1

HVIN: 003-0454-13

132-3295-000

Artwork: 132-3295-000

Revision A

5.385" x 2.31" x .04" (W x H x R)

Shown at 100%

ECN: 54123

12 February 2021