



Dali Wireless, Inc.

535 Middlefield Road, Suite 280

Menlo Park, CA 94025

<http://www.daliwireless.com>

April 9th, 2015

Timco Engineering, Inc.
849 N.W. State Road 45
P.O. Box 370
Newberry, Florida 32669 USA

Reference: Attestation Regarding Warning Labels

FCC ID: HCOT30SNI1A

This letter is an attestation that the warning label and class B messages required per 47 C.F.R. § 90.219 will be affixed to the unit, on the outside packaging, in print and on-line versions of the owner's manual and installation instructions, and in on-line point-of-sale marketing materials. A sample of this label is included in the exhibit named "t30SNI1NB -LabelSmpl-vX.pdf".

A handwritten signature in black ink, appearing to read "Shawn Stapleton", with a long horizontal line extending to the right.

Shawn Stapleton
Founder and CTO