

Honeywell International Inc

9680 Old Bailes Rd, Fort Mill, South Carolina, 29707, United States

Tel: 315 554 6000 ; Fax: 315 554 6000

Date: October 20, 2015

FCC Laboratory
7435 Oakland Mills Rd.
Columbia, MD 21046

SUBJECT: FCC Application for FCC ID: HD5-99EXBF

In accordance with §15.407(j), we acknowledge that should any harmful interference generated by FCC ID: HD5-99EXBF to licensed services in 5.15-5.25 GHz, corrective action is required to be taken. Corrective actions may include reducing power, turning off devices, changing frequency bands, and/or further reducing power radiated in the vertical direction.

Sincerely yours,



Michael Robinson
michael.robinson3@honeywell.com