

Appendix F. SAR Test Setup Photos

Body-worn Exposure Condition (AlphaNumeric)



Front at 15 mm



Back at 15 mm



Front with Holster 1 at 0 mm



Left Side with Holster 2 at 0 mm

Product Specific Exposure Condition (AlphaNumeric)



Front at 0 mm



Back at 0 mm



Right Side at 0 mm



Left Side at 0 mm



Top Side at 0 mm



Bottom Side at 0 mm

PD Exposure Condition (AlphaNumeric)



Front at 2 mm



Back at 2 mm



Left Side at 2 mm



Right Side 2 at 0 mm