

Honeywell International Inc
9680 Old Bailes Rd, Fort Mill, South Carolina, 29707, United States

Federal Communications Commission
7345 Oakland Mills Road
Columbia MD 21046

Date: December 25, 2025

SUBJECT: Request for Class II Permissive Change for FCC ID: **HD5-CT45PL1NE**

The product, Mobile Computer, has been granted by FCC dated 11/04/2021, FCC ID: **HD5-CT45PL1NE**. Pursuant to §2.1043, we, (Honeywell International Inc), would like to modify the authorized equipment for below changes:

#1 : The software change list is described as following:

- ✓ Non-HLOS & FSG changes for modified RF parts
- ✓ SW changes to support old and new display dynamically with single build
- ✓ SW changes to support old and new sensors in same build

#2: For HW changes:

Some components have been declared EOL. We have found the replacement alternate parts as the following:

Description	Alternate Part No.	Alternate part	Alternate Part Vendor
SP3T Switch	BHW30001041	SKY13582-676LF	Skyworks
SPDT Switch	BHW30001021	BGS12P2L6	Infineon
SP4T Switch	BHW30001031	BGS14M8U9	Infineon
RF Filter	BHZ50001431	B39222M5012D310	Qualcomm
RF Filter	BHZ50001421	B39222M5011D310	Qualcomm
Sensor	BA200001842	FPS3-ALS-RISE	borqs
EMI Filter	BHZ30000231	UM8611	UNION SEMI
EMI Filter	BHZ30000241	UM4611	UNION SEMI
Sensor	BHW50000701	AK09919C-L	AKM
Diversity Module	BHW30001011	QDM2330	Qualcomm

Except for the changes above, no other modification is performed.
These changes are consistent with FCC Class II Permissive Change requirements.

Thank you for your attention in this matter.

Sincerely,

A handwritten signature in black ink that reads "Cindy Jiang". The script is cursive and fluid, with the first letters of each name being capitalized and prominent.

Contact Name: Cindy Jiang
Honeywell International Inc
Tel: +86(512)82258162
Fax: +86(512)62571517
E-mail: Cindy.Jiang@honeywell.com