



Honeywell International Inc

Honeywell Sensing & Productivity Solutions
9680 Old Bailes Road
Fort Mill, SC 29707 USA

Date: November, 9, 2015

FCC Laboratory
7435 Oakland Mills Rd.
Columbia, MD 21046

Subject: FCC Class II Permissive Change
FCC ID: HD57800LG; HD57800LW; HD57800LO; HD57800LC

To Whom It May Concern,

This is to request a Class II permissive change for FCC ID: HD57800LG; HD57800LW;
HD57800LO;
HD57800LC originally granted on 11/27/2011; 11/18/2011; 11/29/2011; 03/13/2012

The major change field under this application is as follows:

- Test this device in accordance with the Part 15 rules for U-NII devices released on June 2014.

Best Regards,

A handwritten signature in blue ink that reads "Michael Robinson".

Michael Robinson
Product Compliance
Michael.Robinson3@honeywell.com
(800) 782 4263 telephone USA
+1-315-554-6387 telephone international