



Honeywell International Inc
Honeywell Sensing & Productivity Solutions
9680 Old Bailes Road
Fort Mill, SC 29707 USA

Date: November, 4, 2015

FCC Class II Permissive change Request

This is to request a Class II permissive change for FCC ID: HD599EXLW originally granted on 03/02/2011.

The major change field under this application is as follows:

- 1) This device is tested in accordance with the Part 15 rules for U-NII devices released on June 2014.

Best Regards,

A handwritten signature in blue ink that reads "Michael Robinson".

Michael Robinson
Product Compliance
Michael.Robinson3@honeywell.com
(800) 782 4263 telephone USA
+1-315-554-6387 telephone international