

Acer Incorporated

8F, 88, Sec 1, Hsin Tai Wu Rd, Hsichih, Taipei Hsien, Taiwan
Tel: 886-2-6606-3131 Ext: 3811 ; Fax: 886-2-2696-3535

Federal Communications Commission
Authorization and Evaluation Division
1435 Oakland Mills Road
Columbia, MD 21046


SUBJECT: Class II Permissive Change for FCC ID: HLZ9560D2W;
Class IV Permissive Change for IC: 1754F-9560D2W, Model: 9560D2W.

The product, Intel Dual Band Wireless-AC 9560, has been granted by FCC dated 04/27/2018, FCC ID: HLZ9560D2W and been granted by IC dated 04/28/2018, IC : 1754F-9560D2W. The intension of this application is to enable the modular certified FCC ID: HLZ9560D2W and IC: 1754F-9560D2W to be integrated in Notebook Computer, Model: N17H2.

The module installed into host platform mentioned above is electronically and mechanically identical to the original certified module. The original FCC testing on module the antenna was connected to the module in an open environment. The current host platform under application uses and antenna of the same type but different gain and is installed inside the host platform enclosure. Since the different antenna, we performed below items.

1, for DSS/ DTS/U-NII-1/U-NII-2A/U-NII-2C/U-NII-3, verified conducted power, the power of each band is lower than original, only conducted emission and RSE was retested.

Should you have any questions or comments regarding this matter, please have my best attention.
Sincerely yours,



Contact Person: RU Jan

Company: Acer Incorporated

TEL: 886-2-8691-3289

FAX: 886-2-8691-3120

E-mail: Ru.jan@acer.com