







UNIT PARTIALLY DISASSEMBLED



51694AC CPU BOARD SIDE 1



51694AC CPU BOARD SIDE 2



**4065/8A ProxPoint OEM Module
Bottom View**

