



Appendix C

Date: 2016-02-22

Report Number: 60.790.16.011.01

Model No.: RDWL917A





Appendix C

Date: 2016-02-22

Report Number: 60.790.16.011.01

Model No.: RDWL917A



Page 2 of 10

TÜV SÜD Hong Kong Ltd.



3/F, West Wing, Phase 2, 10 Science Park West Avenue, Hong Kong Science Park, Shatin, Hong Kong

Appendix C

Date: 2016-02-22

Report Number: 60.790.16.011.01

Model No.: RDWL917A





Appendix C

Date: 2016-02-22

Report Number: 60.790.16.011.01

Model No.: RDWL917A



Page 4 of 10

TÜV SÜD Hong Kong Ltd.



3/F, West Wing, Phase 2, 10 Science Park West Avenue, Hong Kong Science Park, Shatin, Hong Kong

Appendix C

Date: 2016-02-22

Report Number: 60.790.16.011.01

Model No.: RDWL917A





Appendix C

Date: 2016-02-22

Report Number: 60.790.16.011.01

Model No.: RDWL917A





Appendix C

Date: 2016-02-22

Report Number: 60.790.16.011.01

Model No.: RDWL917A



Page 7 of 10

TÜV SÜD Hong Kong Ltd.



3/F, West Wing, Phase 2, 10 Science Park West Avenue, Hong Kong Science Park, Shatin, Hong Kong

Appendix C

Date: 2016-02-22

Report Number: 60.790.16.011.01

Model No.: RDWL917A



Appendix C

Date: 2016-02-22

Report Number: 60.790.16.011.01

Model No.: RDWL917A

