



12 December 2006
Ref: US000135

To FCC

BABT
Balfour House, Churchfield Road
Walton on Thames
Surrey, KT12 2TD
United Kingdom
Telephone: +44 (0)1932 251200
Fax: +44 (0)1932 251201
Direct Dial: +44 (0)1932 251227
E-mail: Hilton.Carr@babt.com
Website: www.babt.com

Overall Assessment Letter for Honeywell RTUK12
FCC id: HS9-RTU-K12

I have reviewed this composite application and find it compliant
This is an application for an RFID Reader used for door entry etc

Please note the following:

1: RF Exposure

The Equipment is categorically excluded from routine evaluation and falls below the low threshold. As a consequence no RF evaluation has taken place.

2: Part 15 Clause 15.203

While not explicitly reported within the Test report there is ready evidence within the application showing that the Antenna is internal to the equipment and not able to be changed without invalidating the grant.

2: Part 15 Clause 15.205

While not explicitly reported within the Test report the results for Clause 15.209 demonstrate that the equipment is compliant to this requirement.

Yours sincerely

Hilton Carr
Task Manager, Certification and Technical Development

