

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 210
HSW-2450
4492A-2450
17-0308
April 24, 2018
Murata Electronics North America
WIT2450

EXTERNAL PHOTOGRAPHS




Figure 1. Top of EUT

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 210
HSW-2450
4492A-2450
17-0308
April 24, 2018
Murata Electronics North America
WIT2450




Figure 2. Bottom of EUT

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 210
HSW-2450
4492A-2450
17-0308
April 24, 2018
Murata Electronics North America
WIT2450



Figure 3. DC Input Side of EUT

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 210
HSW-2450
4492A-2450
17-0308
April 24, 2018
Murata Electronics North America
WIT2450




Figure 4. RF Output Side of EUT

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 210
HSW-2450
4492A-2450
17-0308
April 24, 2018
Murata Electronics North America
WIT2450

ANTENNA PHOTOGRAPHS



Figure 5. 9 dBi Omni Antenna

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 210
HSW-2450
4492A-2450
17-0308
April 24, 2018
Murata Electronics North America
WIT2450




Figure 6. 9 dBi Corner Antenna

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 210
HSW-2450
4492A-2450
17-0308
April 24, 2018
Murata Electronics North America
WIT2450




Figure 7. 4 dBi Patch Antenna, Front Side

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 210
HSW-2450
4492A-2450
17-0308
April 24, 2018
Murata Electronics North America
WIT2450



Figure 8. 4 dBi Patch Antenna, Connector Side