

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 210
HSW-2450
4492A-2450
17-0308
April 24, 2018
Murata Electronics North America
WIT2450

TEST CONFIGURATION PHOTOGRAPHS




Figure 1. Radiated Emissions Test Setup, Front, Omni Antenna

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 210
HSW-2450
4492A-2450
17-0308
April 24, 2018
Murata Electronics North America
WIT2450




Figure 2. Radiated Emissions Test Setup, Front, Corner Antenna

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 210
HSW-2450
4492A-2450
17-0308
April 24, 2018
Murata Electronics North America
WIT2450




Figure 3. Radiated Emissions Test Setup, Front, Patch Antenna

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 210
HSW-2450
4492A-2450
17-0308
April 24, 2018
Murata Electronics North America
WIT2450




Figure 4. Radiated Emissions Test Setup, Back, Omni Antenna

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 210
HSW-2450
4492A-2450
17-0308
April 24, 2018
Murata Electronics North America
WIT2450




Figure 5. Radiated Emission Test Setup, Back, Corner Antenna

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 210
HSW-2450
4492A-2450
17-0308
April 24, 2018
Murata Electronics North America
WIT2450




Figure 6. Radiated Emission Test Setup, 1 meter, Corner Antenna

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification/ RSS 210
HSW-2450
4492A-2450
17-0308
April 24, 2018
Murata Electronics North America
WIT2450




Figure 7. Radiated Emission Test Setup, Back. Patch Antenna