

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission **(Below 1GHz)**



Photo 1



Photo 2

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Radiated Spurious Emission
(Above 1GHz)




Photo 1




Photo 2

Worst Case Position

Below 1 GHz: (Horizontal: Z-axis / Vertical: Y-axis)

Above 1 GHz: (Horizontal: Y-axis / Vertical: Z-axis)

X-axis



Y-axis



Z-axis



Worst Case Position



With mechanical key inserted (Worst)



Without mechanical key inserted

End of Report