

APPENDIX 3: Photographs of test setup

Radiated Emission Below 1GHz (Internal Antenna)




Photo 1




Photo 2

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

Radiated Emission
Above 1GHz (Internal Antenna)




Photo 1




Photo 2

Radiated Emission
Below 1GHz (External Antenna)




Photo 1




Photo 2

Radiated Emission
Above 1GHz (External Antenna)




Photo 1





Photo 2

Worst Case Position
(Horizontal: X-axis / Vertical: X-axis)
Internal Antenna

X-axis



Y-axis



Z-axis




Worst Case Position

Receiver (Horizontal: X-axis / Vertical: X-axis)

Antenna (Horizontal: X-axis / Vertical: X-axis)

External Antenna

X-axis



Y-axis



Z-axis



X-axis



Y-axis



Z-axis



End of Report

UL Japan, Inc.

Ise EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124